

SHD100/SHD101 Humidity Transmitter for Duct Mounting 0-10 V/4-20 mA

SHD100 is an active sensor, which measures the relative humidity (%RH) and converts the measurement into an electric current 4–20 mA or a voltage level 0–10 V.

The transmitter is delivered as a complete unit, comprising an aluminum mounting flange with the sensing element and an amplifier mounted in a separate housing.

The SHD100-T is equipped with passive temperature elements - user selectable NTC 1.8 or 10 k Ω . The NTC 1.8 k Ω is for Vista products, while the NTC 10 k Ω is for I/NET products.

The SHD100-T5 is equipped with passive temperature elements - user selectable NTC 1.8 or 10 k Ω . The NTC 1.8 k Ω is for Vista products, while the NTC 10 k Ω is for continuum products.

The SHD100-T6 incorporates the 5.02 kΩ NTC network (@ 25°C) for use with Satchwell products and BMS systems.

All SHD100 products are intended for immersion installation and can be used for relative humidity measurement in air ducts.

FEATURES

Selectable 4-20 mA, 0-10V

TEMPERATURE DEPENDENCE

- +/- 2% accuracy
- 24Vac / 15...36 Vdc power
- Optional selectable NTC 1.8 and 10 k Ω for TAC Vista, I/NET and continuum
- Optional NTC 5.02 k Ω (@ 25°C) for Satchwell products and BMS systems
- M20 gland nut supplied for conduits





DIMENSIONS

Dimensions in mm (in.)

ACCURACY

NTC 1.8 kohm for Vista Products		
±0°C/32°F±0.5°C/±0.9°F		
25 °C/77 °F±0.3 °C/±0.5 °F		
50 °C/122 °F±0.6 °C/±1.1 °F		
100 °C/212 °F±1.3 °C/±2.3 °F		

–25℃ / –13°F	±0.5℃ / ±0.9°F
±0°C / 32°F	±0.2℃ / ±0.4°F
25°C / 77°F	±0.2°C / ±0.4°F
50°C / 122°F	±0.2℃ / ±0.4°F
70°C / 158°F	±0.2℃ / ±0.4°F
100°C / 212°F	±0.5°C/±0.9°F

NTC 10 kohm for Continuum ™ Product
-25°C/-13°F±0.5°C/±0.9°F
±0°C / 32°F±0.2°C / ±0.4°F 25°C / 77°F±0.2°C / ±0.4°F
50°C / 122°F±0.2°C / ±0.4°F 70°C / 158°F±0.2°C / ±0.4°F
100°C/212°F±0.5°C/±0.9°F

NTC 5.02 kohm for Satchwell	™ Product
-----------------------------	-----------

-25°C/-13°F±0.6°C/±1.0°F
±0°C / 32°F±0.3°C / ±0.5°F
25°C / 77°F±0.2°C / ±0.4°F
50°C / 122°F±0.2°C / ±0.4°F
75°C / 167°F±0.3°C / ±0.5°F
100°C/212°F±0.3°C/±0.5°F



INSTALLATION

4-20mA

Note! The wires must be connected in the correct way.

The sensor must not be touched since it is sensitive to mechanical damage and to grease etc. from the fingers.

The transmitter is connected with a 2-wire cable. The current is proportional to the measured humidity and it is measured over an external load resistance R L. The supply voltage UM is a function of the voltage across the room transmitter UG and the voltage drop across the load resistor and the wire resistances.



0-10 V

The transmitter is connected with a 3-wire cable. If another load is to be connected close to the sensor, this should be made with a separate Go, so that the measuring signal will not be affected.



WIRING



SHD100-T and SHD101-T5



UG=15&36 VDC/24 VAC ± 10%

UG=15...36 VDC / 24 VAC ± 10%

SHD100-T6 and SHD101-T6 4...20mA / 0...10V 0...100%r.H.



SPECIFICATIONS SHD 100/SHD 101

Time Constant	<15 s (depending on air circulation)
Accuracy	± 2% RH
Temp dep, - 10 to + 60 ^o C (figure on page 1)	$<\pm$ 0.3% RH (worst case, at 90% RH, D %RH will be less at lower %RH)
Max. Inaccuracy After 5 Years	< ± 3% RH
Operating Range	0-95% RH
Operating Temperature	-10 to 60 oC (14 to 140 °F)
Storage Temperature	-40 to 60 ^o C (14 to 140 ^o F)
Sensor Element for SHD100-T and SHD 101-T5	NTC, 1.8 k Ω at 25 °C (77 °F) and NTC, 10 k Ω at 25 °C (77 °F)
SHD101-T6	NTC, 5.02 kΩ at 25 °C (77 °F)
Immersion Well and Housing	Polyamide Plastic
Protective Filter for Sensor	Bronze
Enclosure Rating	IP 65
Weight	165 g (0.364 lb.)
EMC Standard	EN 50081-1, EN 50082-1

-20 mA	
Current Output 0-100% RH	0-20 mA
Voltage Across Sensor	UG max. 28 (36) V DC, UG min. 15 V DC At a 36 V DC supply accuracy decr. with about 1% RH.
Maximum Load (Ω)	R = (UM - 15)/0.02

0-10 V	
Voltage Output 0-100% RH	0-10 V
Power Supply	15-35 V DC or Alternating 24 \pm 10% V AC
Current Consumption, Typical	10 mA
Load Resistance	>20 kΩ

ORDERING INSTRUCTIONS

MODEL	PART NUMBER
SHD100	0-069-0232-0
SHD100-T	0-069-0233-0
SHD101-T5	0-069-0238-0
SHD101-T6	0-069-0241-0

Copyright © 2007, TAC

All brand names, trademarks and registered trademarks are the property of their respective owners. Information contained within this document is subject to change without notice. All rights reserved.

PART NUMBER 03-00109-01-en



Europe / Headquarters Malmö, Sweden +46 40 38 68 50 Americas Dallas, TX +1 972-323-1111 Asia-Pacific Sydney, Australia +61 (0) 2 8336 6100

www.tac.com

